




Cooling shrouds 3" & 4"











de Montageanleitung
en Installation instructions
fr Notice de montage
nl Montagehandleiding
es Manual de instalación
it Istruzioni di montaggio
pt Manual de montagem
el Οδηγίες συναρμολόγησης
tr Montaj kılavuzu
sv Monteringsanvisning
no Monteringsveiledning
fi Asennusohje
da Installationsvejledning

hu Szerelési útmutató
pl Instrukcja montażu
cs Návod k montáži
ru Инструкция по монтажу
et Paigaldusjuhend
lv Montāžas instrukcija
lt Montavimo instrukcija
sk Návod na montáž
sl Navodilo za montažo
bg Инструкция за монтаж
ro Instrucțiuni de montaj
hr Upute za montažu
sr Uputstvo za montažu
uk Керівництво з монтажу
mk Упатства за поставување
ar تعليمات التثبيت




L	=>	L1
350	=>	120
500	=>	195
750	=>	320
850	=>	370
1000	=>	445









5. 








6. 








+




1. ... 5. =








6.





7.





wilo

Pioneering for You



Local contact at
www.wilo.com/contact

WILO SE
Wilopark 1
44263 Dortmund
Germany
T +49 (0)231 4102-0
T +49 (0)231 4102-7363
wilo@wilo.com
www.wilo.com